

FIG. 1




FIG. 2

1054460.013001





FIG. 3a





FIG. 4a





FIG. 5a





FIG. 6a

202210-09115001



FIG. 7




FIG. 8




FIG. 9




FIG. 10

METERING PUMP WITH PROPORTIONAL OUTPUT




FIG. 11




FIG. 12




FIG. 13

0054450.03003  
2022100914500F



FIG. 16




FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 18a




FIG. 18b




FIG. 18c

FIG. 18a




FIG. 19




FIG. 19a




FIG. 19b




FIG. 19c

2025-10-09 14:50:01




FIG. 20




FIG. 21







FIG. 22










09850-013001






FIG. 26

202210"0911500F




FIG. 28




FIG. 28a





FIG. 28b



202209475001




FIG. 29




FIG. 29a

FIGURE EIGHT MOTION OF PISTON ARMS  
 CROSS U-JOINT, WORST CASE DEVIATION






FIG. 30





2022100915001




FIG. 32




FIG. 32a




FIG. 33

2022FO-0347500T






FIG. 34

2022-10-09 15:00






FIG. 36








FIG. 37


2025-10-09 14:50:01











**FIG. 41**

[illegible]






FIG. 43

202270-09475001




FIG. 44

2022FO 031T500F

**FIG. 45**





FIG. 46






FIG. 47




FIG. 48




FIG. 49

202610-09850-013001






FIG. 50




FIG. 51




FIG. 53





FIG. 52



**FIG. 54**




FIG. 55




FIG. 56

FIG. 56B




FIG. 56A








FIG. 56C










Fig. 57




Fig. 58

2025-09-10 09:13:00




Fig. 58

09850-013001